


COPYRIGHT: ITHACA TOMPKINS REGIONAL AIRPORT 2002

Ithaca Tompkins Regional Airport Runway 14-32 Extended Safety Area Analysis

Design Deficiencies

Ithaca Tompkins Regional Airport
September, 2002




**Ithaca Tompkins Regional Airport Runway 14-32
Extended Safety Area Analysis**

**Approach Runway 32 Object Free Area &
Safety Area Deficiency**



**Figure
2**




**Ithaca Tompkins Regional Airport Runway 14-32
Extended Safety Area Analysis**

**Approach Runway 14 Object Free Area
Deficiency**



Figure
3



**Ithaca Tompkins Regional Airport Runway 14-32
Extended Safety Area Analysis**

**Runway Centerline to Taxiway Centerline
Deficiency**



Figure
4